Work Ord Tuesday, June 2												Page 1
Item ID: Revision ID: Item Name:	D4042-5			Accept					Setup S	Start Stop		
Start Date: Required Date: Reference:	6/22/2010	Start Qty: 1.00 Req'd Qty: 1.00			Cust Item II Customer:	D:						
Approvals:	Process Pla	n: <u> </u>	Date:	Tooling: _ SPC (Y/N):	Da					Start Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejec Qty		eject umber	Insp. Stamp
Draw Nbr D4042	Rev A	ision Nbr				<u>.</u>						•
100 Large Fab Large Fab		Memo 1- Cut as po 2- Deburr a	er dwg D4042 nd remove identification m	0.00 0.00 SAO arkings	10-06	-23		(b)	>			
110 QC Quality Control		QC5- Inspect part comp	leteness to step on W/O	0.00	.63			0				

120

Packaging

Packaging

Memo

Identify as per dwg & Stock Location: Beskel

0.00

0.00

© 10.06.23

W/O: WORK ORDER CHANGE								
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1 TOO WGI	
								 - -
						1		
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQA : _	Date: _	
	R	esolution:					Date: _	
NCR:			VORK ORI	DER NON-CONFORMA	NCE (NCF	R)		
DATE	STEP	Description of NC	4 11 4	Corrective Action Section		Verification		Approval
DAIL	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		Chief Eng	QC Inspector
							į	
	1	ŀ	1		1		1	I

Work Order ID 60014

Tuesday, June 22, 2010 3:22:56 PM



Page 2

Item ID:

D4042-5

Accept



Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Required Date: 7/30/2010

Rib

QC:

6/22/2010

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Operation

Date:

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Start

Stop



Sequence ID/

Work Center ID

Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Number Qty

Insp. Stamp

130

Memo

0.00

Run

Quality Control

10/06/24 M



W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CH	ANGE	,	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								•			
				11814							
	-	·									
Part No	:	PAR #:	Fault Cat	egory:	NO	R: Yes	No DQA		Date:		
•	R	esolution:	Dispositi	on:	Q/	A: N/C CI	osed:		Date:		
NCR:		V	VORK ORI	DER NON-CONFO	RMANC	E (NCF	()				
DATE	STEP	Description of NC	Corrective Action S Initial Action Description			Sign 8	Verifica		Approval Chief Eng	Approval	
		Section A	Chief Eng	Chief Eng	uon	Date	Sectio	n C	Chief Eng	QC Inspector	
						·					
							`				

Picklist Print

Tuesday, June 22, 2010 3:23:01 PM

Work Order ID: 60014

Parent Item: D4042-5

Parent Item Name: Rib



Start Date: 6/22/2010

Required Date: 7/30/2010

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: new issue DD 10.01.07 verified by:EC revA DD 10.02.18 verified by:EC

IPP Rev:B as per dwg

•	10.02.10	vermed by .be											
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.750W.049	· · · · · · · · · · · ·	Purchased	No			100	f	446.7945	5.333	5.613684 SAD		0-00	3-23
				Location	!	Loc (<u>Oty</u>	Loc Code					
				MAT		146.794	4919						
					113763		0						
					114323	28.3020	0789						
					114677								

Location	Loc Qty	Loc Code	
MAT	146.7944919		
113763	0		
114323	28.3020789		
114677	14.34201		
114835	104.150403		5.613687
MAT017	3.68448E-05		
114298	3.6845E-05		
WA	300	•	
114992	300		

W/O:	·		WO	RK ORDER CHANG	ES				†	
DATE	STEP	PRO	OCEDURE CHAN	GE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	-						,			
Part No	•	PAR #:	Fault Categ	ory:	_ NCR: Yes	s No DQA: Date:				
	R	esolution:	Disposition		_ QA: N/C Cld	osed:		Date: _		
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)				
DATE	STEP	Description of NC	Initial		ion B Sign &		cation		Approval	
5/112	0.2.	Section A	Chief Eng	Action Description Chief Eng	Date	Sect	tion C	Chief Eng	QC Inspector	
				,						
	·									
				·						
									1	

8 (11)(10)(9)

		2	1
ITEM	QTY -041	P/N	DESCRIPTION
	Х	D4042-041	SHORT BASKET BASE ASSY, LH
1	1	D4042-101	BASKET BASE FRAME ASSY, LH
2	3	D4045-1	LUG
3	1	D4046-1	MESH BASKET BASE
4	1	D4046-3	MESH FWD END
5	1	D4046-5	MESH AFT END
6	3	D4016-1	HINGE HALF, BASE
7	4	D4021-1	HANDLE PLATE
8	2	D2581	MOUNTING BRACKET
9	2	D2931	BUMPER
10	2	AN960JD8	WASHER
11	2	MS20600AD4W3	RIVET

SHOOT RECORD OF CALIFIELKING. UNION PROTEIN SUBJECT TO AMEE ... WITHOUT NOTICE WORK ORDER NO. 60014 BS10-6-22



Α	NEW ISS	UE		RF	10.01.29						
REV.	DESCRIP	TION		BY DATE							
DESIG	N	RF	DART AFROSP	DART AEROSPACE LTD							
DRAWN RF			HAWKESBURY, ONTARIO, CANADA								
CHECKED (7)			DRAWING NO.	REV. A							
MFG. A	PPR.	\overline{R}	□ D4042	5	SHEET 1 OF 11						
APPRO	OVED	140	TITLE	SCALE							
DE APPR.			SHORT BASKET BASE ASSY NTS								
DATE	10.0	1.29	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS								

D4042-041 SHORT BASKET ASSY, LH (MESH SHOWN LOCALLY FOR CLARITY)

С

NOTES:
1) MATÉRIAL: N/A
2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: 28.82 Ibs APROX
8) INSTALL AFTER FINISH
9) TRIM LOCALLY AS REQUIRED TO CLEAR FASTENERS/STRUCTURE
10) WELD PER DART QSI 004

8


3

W/O:			WC	RK ORDER CHANGI	ES					
DATE	STEP	PRC	CEDURE CHAI	NGE	Ε	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						Ī				1
Part No		PAR #:	Fault Cate	norv.	NCR.	Yes N	lo DO	Δ-	Date:	
			Disposition: QA: N/C Closed: Dat							
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCR))			·
DATE	STEP	Description of NC		Corrective Action Section		Sign &		cation	Approval	Approval
	O.L.	Section A	Initial Action Description Chief Eng Chief Eng			Date	Secti	ion C	Chief Eng	QC Inspector

QTY -042 ITEM P/N DESCRIPTION X D4042-042 SHORT BASKET BASE ASSY, RH D4042-102 BASKET BASE FRAME ASSY, RH D4045-1 MESH BASKET BASE MESH FWD END D4046-1 4 D4046-3 D4046-5 MESH AFT END 6 D4016-1 HINGE HALF, BASE D4021-1 HANDLE PLATE 8 D2581 MOUNTING BRACKET D2931 BUMPER 10 AN960JD8 WASHER MS20600AD4W3 RIVET

D

С



D4042-042 SHORT BASKET ASSY, RH (MESH SHOWN LOCALLY FOR CLARITY)

D

NOTES:
1) MATÉRIAL: N/A
2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: 28.82 ibs APROX

7) WEIGHT 20.02 IDS AFROA 8) INSTALL AFTER FINISH 9) TRIM LOCALLY AS REQUIRED TO CLEAR FASTENERS/STRUCTURE 10) WELD PER DART QSI 004

DESIGN	RF	DART AEROSPACE LTD					
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA					
CHECKED	a	DRAWING NO.	REV. A				
MFG. APPR.	R	D4042 SHEET	2 OF 11				
APPROVED	140		SCALE				
DE APPR.	-#-	SHORT BASKET BASE ASSY	NTS				
DATE 10.0	1.29	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENTS PRIVATE AND CONFEDENTIAL AND IS SUPPLIED ON THE EXPRESS CONCENDED THAT IT IS MIT TO BE USED FOR ANY REPORTED CONCENDED.					


3

8


5

3


W/O:	1		WC	ORK ORDER CHANG	GES					***************************************
DATE	STEP	PRO	OCEDURE CHA			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									10.00	
					E .					
			·							
Part No	:	PAR #:	Fault Cate	gory:	NCR:	:Yes N	lo DQ .	A:	_ Date: _	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			ction B	0: 0		cation	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	on C	Chief Eng	QC Inspector
						·				
	į									
										,
										-




	•									
W/O:			ES					1		
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	[Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Ye	es No	DQ.	A:	_ Date: _	
	R	esolution:	Dispositi	on:	QA: N/C	Clos	ed:		Date:	
NCR:		1	WORK ORE	DER NON-CONFORMA	ANCE (N	CR)				
DATE	STEP	Description of NC			ion B			ation	Date:Date:	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti	on C	Chief Eng	QC Inspector
	i.									




W/O:	•		W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
]		
								.A., P =	
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	\ :	Date:	
	Re	esolution:	Dispositi	on:	QA: N/C Closed: Date:				
NCR:			WORK ORE	DER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC			ion B	Verific		Approval	Approval
DAIL	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector
					9				




W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PROCEDURE CHANGE			Ву	D	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							3			
									•	
							,			
Part No	:	PAR #:	Fault Categ	jory:	NCR: Ye	es No	DQA	\:	Date:	
	R	esolution:	Disposition	Disposition: QA: N/C Closed: Date:						
NCR:		1	WORK ORDE	R NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC		ction B	0	Verification			Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	n & ate	Section	on C	Chief Eng	QC Inspector
									:	
					i					




W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
					ļ					
				•	ĺ	,				
			-			į				
Part No	Part No: PAR #:			egory:	NCR: Yes No DQA: Dat					
	Re	esolution:	Dispositi	on:	QA: N/C Closed: Date:					
NCR:			WORK OR	DER NON-CONFORMA	ANCE (NO	CR)				
DATE	STEP	Description of NC	Corrective Action Section B			Veri	fication	Approval	Approval	
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig: Da	1&r ∣ _{Se}	ction C	Chief Eng	QC Inspector	
							**************************************	,,		
1						1		1		




W/O:	-		W	ORK ORDER CHANGI	ES				,
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				1					
	!								
							!		
						į			
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA	\:	Date:	
				Disposition: QA: N/C Closed: Date:					
NCR:		\	WORK OR	DER NON-CONFORMA	NCE (NCR	R)			
DATE	STEP	Description of NC Corrective Action			Section B Sign & Section 0				Approval
DAIL	OIL.	Section A	Initial Chief Eng	Action Description Chief Eng	Date	Section	on C	Chief Eng	QC Inspector
									}
	1								



W/O:			W	ORK ORDER CHANGE	ES			18.18.11	
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Proa Mgr	
							:		
									:
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:		_ Date: _	
	Re	esolution:	Dispositio	Disposition: QA: N/C Closed: Date: _					
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	0750	Description of NC		Corrective Action Section		Verificat	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
					1		l l		
						. 1	į		
					:				




W/O:			WC	RK ORDER CHANG	ES		,		· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									<u></u>
									- · .
								,	
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:		Date:	
	Re	esolution:	Disposition	າ:	_ QA: N/C Cld	sed:		Date: _	·
NCR:		· · · · · · · · · · · · · · · · · · ·	WORK ORDI	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section B			tion		Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	ı C	Chief Eng	QC Inspector
		,			-				
	I	1	1		I .			1	1



Dart Ae	rospace	Ltd							
W/O:		45-44-1	WC	RK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Зу	Date Qt	y Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR:	Yes N	lo DQA: _	Date: _	1
	Re	esolution:	Dispositio	າ:	_ QA: N	I/C Clo	sed:	Date: _	
NCR:		1	WORK ORDI	ER NON-CONFORMA	ANCE (NCR))		
DATE	STEP	Description of NC	Corrective Action Section			Sign &	Verification		Approval
	5121	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section C	Chief Eng	QC Inspector

	WORK ORDER NON-CONFORMANCE (NCh)									
	Description of NC	Corrective Action Section B			Verification	Approval	Approval			
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
				į						
		·								
	STEP	STEP Description of NC Section A	STEP Description of NC Section A Initial	STEP Section A Initial Action Description	STEP Section A Initial Action Description Sign &	STEP Description of NC Initial Action Description Sign & Section C	STEP Description of NC Initial Action Description Sign & Verification Approval Section C Chief Eng			



W/O:			WC	RK ORDER CHANGES		•)
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						1-		F100 Wigi	
								:	}
Part No	:	PAR #:	Fault Cate	NCR: Yes No DQA: Date:					
	Resolution:			n: (QA: N/C Closed: Date:				
NCR:		,	WORK ORDI	ER NON-CONFORMAN	CE (NCR	3)			
DATE	STEP	Description of NC Corrective Action Section			1 1		cation	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	ion C	Chief Eng	QC Inspector
		į.							
		<i>;</i>							
	I				ı	1		ı	1